



[illegible]

NOTE:  
ONLY CONTROL SLAB - NEW FABRICATION  
REPAIR DAMAGED GROOVES AND CANAL INLETS  
CANAL INLET 1 = 28 PCS  
CANAL INLET 2 = 23 PCS