



SLAB / CEILING WORKS:

REPAINT SLAB CEILING WITH FLAT LATEX
REPAIR / RETOUCH WITH PUTTY THE AREAS WHICH HAS CRACK

SLAB / CEILING PLAN
SCALE 1 : 1 0 0 M

ROCKEFELLER 4



R.A. 9266 - Art. 3, Section 20
Drawings and Specifications duly signed, stamped or sealed, as instruments of service are the intellectual properties and documents of the architect, whether the object for which they are made is executed or not. It shall be unlawful for any person, without the consent of the architect or author of said documents, to duplicate or to make copies of said documents for use in the repetition of and for other projects or buildings, whether executed partly or in whole.

PROJECT TITLE:
REPAIR AND IMPROVEMENT ROCKEFELLER 4 & 5
PHILRICE-CES, BRGY, MALIGAYA, SCIENCE CITY OF MUNOZ, NUEVA ECJA

PRODUCED BY:
PHYSICAL PLANT DIVISION
INFRASTRUCTURE UNIT
PHILRICE
SCIENCE CITY OF MUNOZ, NUEVA ECJA

DESIGN:
Arch. RENATO B. BAJIT
PRO DESIGN HEAD
PHILRICE - CES

RECOMMENDING APPROVAL:
ABNER T. MONTECALVO
DED FOR AS-

APPROVED:
JOHN C. DE LEON
EXECUTIVE DIRECTOR
PHILRICE

DESIGNED BY: RBB
DATE: AUG 2019
CADD BY: JRM
DATE: AUG 2019
CHECKED BY: RBB

SHEET NUMBER:
A5